

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

1594 West North Temple - Suite 1210 Box 145801 Salt Lake City, Utah 84114-5801 Telephone: (801) 538-5291 Fax: (801) 359-3940 Tm //21/03

RECEIVED

JAN 1 0 2003

DIV. OF OIL, GAS & MINING

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division

I.	General Information		
	1.	Report Time Period: From (mo./yr.) 1-01-02-To (mo./yr.) 1-01-03	
	2.	DOGM File Number (Mine No): M/023/02Z	
	3.	Mine Name: Topaz Valley Limestone	
	4.	Mineral(s) Mined (or permitted to mine): Limestone	
	5.	Type of mine □ Surface Mine or □ Underground Mine	
	6.	Legal Description (Location of Lands Affected):	
		1/4, <u>SE</u> 1/4, <u>SW</u> 1/4, Section <u>Z/</u> , Township <u>L3S</u> , Range <u>//W</u>	
		1/4, <u>SW</u> 1/4, <u>SE</u> 1/4, Section <u>ZI</u> , Township <u>I3S</u> , Range <u>IIW</u>	
		1/4,1/4, Section, Township, Range	
7.	Name of Operator or Company: Kancho Equipment Services		
	8.	Permanent Street Address: 5626 N 3000W	
		City, State, Zip: De / ta, Wah 84624	
		Phone: 435-864-3971 Fax: 435-864-5192	
	9.	Company Representative (or designated operator):	
		Name: Robert B. Thomas	
		Title: Vice President	
		Business Address: <u>5626 N</u> 3000 W.	
		City, State, Zip: Delta, Utah 84624	
		Phone: 435-864-3971 Fax: 435-864-5192	
		Please check if any of the above information has changed since previous year.	
П.	Mining and Reclamation		
	1.	Was there any mine related activity during the past year? Yes □ No □	
	2.	If no - what was the last year of activity?	
	3.	If yes - how much ore or mineral was mined?	

4.	Briefly describe the type of work performed, volume of material moved, and any new or additional surface disturbances that occurred during the past year.
	pone
5.	How much additional acreage was disturbed during the past year? how
6.	How much acreage was reclaimed during the past year? Resected 18 Acres.
7.	Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results. Put UDOGM approved sceed mix on reclamation area during later part of November.
8.	What is the total disturbed acreage of entire project at years end? 18 acres
9.	Briefly summarize any mining and/or reclamation plans for the upcoming year. I hope we are through with the son-of-a-bitch!!!
<u>NOTE</u> :	Section III., "Additional Information" applies only to large mining operations.
III. Additional	Information - R647-4-121.2 and .3
1.	The operator shall include an updated map depicting surface disturbance and reclamation performed during the year, prepared in accordance with Rule R647-4-105.
2.	The operator shall keep and maintain timely records relating to his performance under the Act, and shall make these records available to the Division upon request.
IV. <u>Signature</u>	Requirement
I here	by certify that the foregoing is true and correct.
	Name (Typed or Print): Robert B. Thomas
	Title of Operator: Vice President
	Signature of Operator: Roll B. Cho
	Date:
jb o:\forms\reports\MR-A	R